ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mananagara Palike

# BBMP ENGINEERING DEPARTMENT

## Road History Data Sheet

### General

| Zone | Ward No. | Ward Name |
|---|---|---|
| YELAHANKA | 9 | Vidyaranyapura |
| **Street ID** | **Street Name** | **Significant Landmark** |
| W0725 | NA | Vacent Land |
| **Segment No.** | **Total Length (m)** | |
| 9/S-W0725/S023153 | 112.98 | |

**Segment Details**

| Seg No. | Length (m) | Start Coordinates | | End Coordinates | | From | To |
|---|---|---|---|---|---|---|---|
| 1 | 112.98 | 77.573028 | 13.068663 | 77.572768 | 13.067675 | Sampige Road | Dead end |

### Work Details

**History of Road / Lane / Circles**

| Name of the Work | Sanctioned Estimated Amount (Rs.) | Sanctioned Year |
|---|---|---|
| Improvements and Asphalting to Roads at 6th Main Dhanalakshmi Layout in Ward No. 09 (Vidyaranyapura) Vidyaranyapura Sub Division. | 1000000 | 2018-19 |
| **Year** | **Type of Work** | **Other Work Type** |
| 2018 - 2019 | Asphalting | |
| **Tender** | **Work Details** | **Job No. / Work Code** |
| Tender | Asphalting to Roads and and Drain Development | 009-20-000008 |
| **Work Order No.** | **Work Order Date** | **Period of Extention** |
| EE/BTP/BBMP/ E-PMT/11 (37105)/WO/173/2019-20 | 12/12/2019 | |
| **Defect Liability Period From** | **Defect Liability Period To** | **Multiple road involved with the same Job No/ Work Code #** |
| 20/03/2020 | 19/03/2021 | No |

### Contractor Details

| Name of Contractor | Contractor Reg No (BBMP/PWD) | Expenditure Booked \ Released (Rs) |
|---|---|---|
| M/s. S.L.V Constructions Prop Sri. Namith. N | | 0.00 |
| **Phone No.** | **E-Mail ID** | |
| 9739986868 | | |

Zone: YELAHANKA Ward No: 9 Ward Name: Vidyaranyapura Street ID: W0725

Date: 29/05/2020 Time: 13:19:06 RH 20200529131906

Vidyaranyapura Sub Division
BBMP, Bangalore - 97

## Field Inspection Details

| Number of Trees | Any Other Information | Name |
|---|---|---|
| 0 | | rudramuni r t |
| **Date of Inspection** | **Remarks** | |
| 27/05/2020 | | |

| Category | Image | Photo Remark |
|---|---|---|
| Drain Condition | | This photo seems out of range. |
| Footpath Condition | | This photo seems out of range. |
| Road Condition | | This photo seems out of range. |
| Segment End | | This photo seems out of range. |
| Segment Start | | This photo seems out of range. |

## Remarks

| Designation | Approver Name | Date | Target Date | Remark |
|---|---|---|---|---|
| CE | S.P.Ranganath | 29/05/2020 | 27/06/2020 | As proposed |
| SE | Vijay Kumar Haridas | 28/05/2020 | 26/06/2020 | Forwarded |
| EE | Mohan Das H T | 27/05/2020 | 26/06/2020 | Verified |
| AEE | Shivakumar M Goudar | 27/05/2020 | 26/06/2020 | Verified |
| AE | Rudramuni R T | 27/05/2020 | 26/06/2020 | Mobile Verification Done |
| AE | Rudramuni R T | 27/05/2020 | 26/06/2020 | Forwarded |

Assistant Executive Engineer
Vidyaranyapura Sub Division
BBMP, Bangalore-97

Zone: YELAHANKA Ward No: 9 Ward Name: Jakkuru Street ID: W0725

Date: 29/05/2020 Time: 13:19:06 RH 20200529131906